

Join the Pest Free Nation! www.PestNation.com

843.867.2807

Termite, Pest, & Rodent Evaluation Report

Thank you for allowing PestNation to evaluate this property. Please note: THIS REPORT IS NOT AN OFFICIAL STATE OF SOUTH CAROLINA WOOD INFESTATION REPORT (CL-100/Termite Letter). OUR OFFICE WILL CONTACT YOU TO VERIFY INFORMATION AND TO SUPPLY YOU WITH THE OFFICIAL STATE REPORT IF NEEDED. Please call us at 843.867.2807 or email us at Office@PestNation.com if you have questions.

DATE: Jul 17, 2021

CLIENT LAST NAME: Sample

ADDRESS (street): 123 Sample St.

CLIENT EMAIL: sample@gmail.com

AGENT EMAIL: sample@gmail.com

PEST INSPECTOR: Eric Jennings
IMAGE OF STRUCTURE:



Termite Findings

This property was inspected for active and/or previous wood destroying organism, pest, and rodent evidence and conducive conditions that may lead to an infestation. This is an inspection of the readily accessible areas of the structure that exist at the time of the inspection. This inspection is not a guarantee or warranty against future or concealed pest, termite, or rodent issues.

This report will include our findings and treatment options for any problems found or for prevention of future problems.

STRUCTURE TYPE: Single Family Crawl

TERMITE INSPECTION FINDINGS: No Activity

LOCATION OF TERMITE FINDINGS: N/A

COMMENTS: Cannot inspect behind fixed ceiling, flooring, wall

coverings, insulation, appliances etc. Possible hidden

infestation and or damage.

DRYWOOD TERMITES:

POWDER POST BEETLES:

None
WOOD BORING BEETLES:

None
WOOD DECAYING FUNGUS (not molds and

None

mildews):

CONDUCIVE CONDITIONS: Wood to Ground Contact

Inadequate Crawl Space Ventilation

Debris in Crawl Space


Inadequate Framing Clearance in Crawl Space

Moisture Issues

OBSTRUCTED OR INACCESSIBLE AREAS: Stored Items in Garage Prevented Full Inspection

PestNation PAGE 2 OF 8

IMAGE OF GRAPH:



IMAGES:







PestNation PAGE 3 OF 8





IMAGE COMMENTS:

Pics 1-3 stored items in garage prevent a full inspection. Possible hidden infestation and or damage.

Pic 4 wood to ground contact at decking components.

Pic 5 framing clearance at crawl door frame in crawl space less than 18" from soil.

Pic 6 moisture issues in door trim

Termite Solutions

Due to the climate in South Carolina, termite protection is recommended even if the structure is currentlyfree of termite activity.

TERMITE TREATMENT RECOMMENDED: Yes, preventative treatment needed

PESTNATION'S SENTRICON SYSTEM w/ \$0.00

ALWAYS ACTIVE INITIAL FEE:

ANNUAL RENEWAL FEE FOR SENTRICON \$0.00

SYSTEM:

LIQUID SPOT TREATMENT NEEDED: N/A

CLICK FOR INFO ON THE SENTRICON https://youtu.be/smnlTvU9WQ0

ALWAYS ACTIVE SYSTEM:

Pest Findings and Solutions

GENERAL PEST FINDINGS: General Crawling Pests

LOCATION OF PEST FINDINGS: Exterior

IMAGES:

PestNation PAGE 4 OF 8





IMAGE COMMENTS:

PEST PREVENTION RECOMMENDED:

PESTNATION'S PESTGUARD INITIAL

SERVICE FEE:

ONGOING PER SERVICE FEE:

SERVICE FREQUENCY:

Spiders

Yes, SC's climate is conducive to pest issues

\$0.00

\$0.00

Every 3 Months

Mosquito Findings and Solutions

MOSQUITO FINDINGS:

Breeding Sites Heavy Vegetation Damp Areas

Conducive Conditions on Property

Conducive Conditions on Neighboring Property

Mosquito Activity During Inspection

IMAGES:







PestNation PAGE 5 OF 8

IMAGE COMMENTS: Harboring sites found

MOSQUITO PREVENTION RECOMMENDED: Yes, SC's climate is conducive to mosquito

issues

PESTNATION'S MOSQUITOGUARD INITIAL

SERVICE FEE:

\$0.00

ONGOING PER SERVICE FEE: \$0.00

SERVICE FREQUENCY: Monthly March - October

MOSQUITO TREATMENT ZONE: 100ft radius around structure

Rodent and Wildlife Findings

EVIDENCE REVEALED: Activity or Previous Activity Observed

Droppings in Attic


SPECIES SUSPECTED: Rats
EVIDENCE LOCATED AT: Attic

ENTRY POINTS OBSERVED: Gaps at Roof Perimeter

IMAGES:







COMMENTS:

Dropping's in attic space over garage

Rodent and Wildlife Solutions

A full exclusion process is the only true way to permanently solve a rodent entry problem. A full exclusion will seal all possible entry points in the structure from the roof to the ground. All other rodent solutions will be temporary in nature because entry points to the structure will still exist. With full exclusion, the rodents will have no possible entry point to the structure and all current rodents inside of the structure will be trapped/removed.

PESTNATION'S FULL RODENT EXCLUSION \$0.00

INITIAL FEE:

WARRANTY: 1 Year

PestNation PAGE 6 OF 8

APPROXIMATE LINEAR FOOTAGE OF GUTTER:

140

GUTTER GUARDS INSTALLED: Partial

Frequently Asked Questions

WHAT IS THE SENTRICON SYSTEM WITH ALWAYS ACTIVE?

Sentricon stations will be placed at strategic locations around the structure. Because termites are constantly forging for a food source, they will eventually find the Sentricon stations. The termites will identify the Sentricon stations as a food source. Each Sentricon station comes loaded with an Insect Growth Regulator that will wipe out the termite colony. Over time, the Sentricon system will gain control over the termite colonies around your structure.

WHAT IS A LIQUID TERMITE TREATMENT?

This will consist of trenching at the foundation of the structure, drilling through attached patios, driveways, and garage floors and applying a liquid termiticide.

WHAT IS A LIQUID SPOT TREATMENT?

This is used in conjunction with the Sentricon system to quickly gain control over termite activity in a specific location. The Sentricon system will be strategically placed around the structure and a liquid spot treatment will be applied at an active termite location.

WHAT IS A DAMAGE/REPAIR WARRANTY?

In the unlikely event that termites infest and do damage to the structure after our treatment, we will re-treat the area and repair any new damage.

WHAT IS A RE-TREATMENT ONLY WARRANTY?

In the unlikely event that termites infest the structure after our treatment, we will re-treat the area. Damage repairs are not included with this type of warranty.

WHAT IS THE SENTRICON WITH DOUBLE DEFENSE TREATMENT?

This is a double layer of protection around the structure that takes advantage of the benefits of both liquid and termite baiting. Sentricon stations will be installed around the perimeter of the structure and a liquid "trench and treat" will be installed at the foundation perimeter.

WHAT ARE CONDUCIVE CONDITIONS FOR TERMITES?

This includes wood to ground contact, inadequate framing clearances in crawl spaces, cellulose debris in crawl spaces, inadequate ventilation in crawl spaces, and moisture issues. It is recommended that as many conducive conditions as possible be eliminated.

WHAT IS PESTNATION'S PESTGUARD?

This is a quarterly inspection and treatment that covers all general crawling pests. On our initial visit, we will conduct a thorough inspection and treatment on the interior and exterior of the structure, including attics and crawl spaces. After the initial visit, we will inspect and treat the exterior perimeter of the structure each quarter. This will stop pests before you see them! Remember, if you ever have a pest issue inside, we will be happy to inspect and treat for you. This service is guaranteed, if pests return, so will we... for free!

HOW DOES PESTNATION'S MOSOUITOGUARD TREATMENT WORK?

Our mosquito service is completed monthly from February to October. All mosquito breeding sites and standing vegetation are treated each month. This will greatly reduce the amount of mosquitoes in your yard. This service is safe for children and pets, but not for mosquitoes. A 100ft radius around your structure will be treated under our standard service. Take back your yard from mosquitoes today!

WHAT IS A RODENT EXCLUSION?

A rodent exclusion service will seal up all possible entry points in your structure from the roof to the ground. Once the home is sealed, rodents remaining inside of the structure will be removed through a

PestNation PAGE 7 OF 8

"one way" door or by trapping. We will return to check the traps until all rodents have been removed. Once complete, the structure will be rodent free and under warranty against re-entry.

Company Information

IMPORTANT NOTE: This report only includes findings from the readily accessible and visible areas of the structure that were present at the time of inspection. In additional to inaccessible areas documented in this report, examples of other inaccessible areas include: crawl spaces that are less than 18 inches in height, areas that have heavy vegetation, areas that have heavy stored items, locked areas, unsafe areas, areas covered by drywall, and areas covered with insulation. The inspector does not move items or insulation and does not dismantle any portion of the structure in order to complete the inspection. There is always the possibility of termite activity/damage in areas that are not accessible to the inspector. Wood destroying organisms may infest or re-infest a structure at any moment. No warranty is provided as part of this inspection. It should be assumed by the client that most structures in South Carolina will experience termite activity at some point. Even if no infestation is visible, the client should budget for a termite treatment and warranty in order to ensure termite protection.

Thank you for allowing PestNation to be a part of your real estate transaction! If you have any questions, please call us at 843.867.2807 or email to Office@PestNation.com

PestNation 843.867.2807 office@PestNation.com www.PestNation.com

PestNation PAGE 8 OF 8